

Latest Vehicle Concern Fixes



Check Engine Lamp with DTC P0089-64	15-16 MY LR4
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• The Check Engine Lamp is illuminated. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• LTB01275 NAS1 has been performed. <p><u>Status:</u></p> <ul style="list-style-type: none">• Ensure the PCM update has been installed and FH22-14C204-TAH.• Perform diagnosis as per TOPlx Workshop Manual.• If diagnosis leads to pump replacement, raise an EPQR so the part can be PRRd.• Include contact information for someone at the retailer who can serve as the point of contact for the shipping company to collect the original pump.	

