


Latest Vehicle Concern Fixes



| | |
|--|--|
| Oil Pan Dowel Pins | 16-19 MY Range Rover, Range Rover Sport, Discovery with TdV6 |
| <p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Noise from starter following removal of the engine oil pan. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• There are dowel pins to properly locate the oil pan. <p><u>Status:</u></p> <ul style="list-style-type: none">• Verify the dowel pins are installed when re-installing the oil pan. |  A technical diagram showing a green oil pan being positioned on a grey engine block. Two purple dowel pins are shown inserted into the engine block to align the oil pan. A dashed line indicates the intended position of the oil pan. |

