

Latest Vehicle Concern Fixes



No Start Due To GWM	19MY Range Rover Velar
<u>Customer Voice:</u> • Customer states the vehicle will not start. <u>Technical Description:</u> • The door locks operate correctly but, when the start/stop button is pressed the vehicle does not start due to the GWM. • When diagnosing with Pathfinder there is no communication with the vehicle. <u>Status:</u> • Under investigation • Should diagnosis lead to the replacement of the BCM / GWM, please raise an EPQR with the parts managers information for us to create a parts return.	A black plastic electronic control unit (ECU) with several multi-pin connectors and a small rectangular label on the right side.

