

**Campaign code.**

L62X-A.05.19.

Subject.

Instrument scoop cover replacement.

Model.

Huracàn EVO.

Model year.

MY 20.

Special or Limited Versions.

All.

Markets.

USA and Europe.

VIN Identification.

ZHWEF4ZF7LLA13201
ZHWUF4ZF3LLA13109
ZHWEF4ZF2LLA13123
ZHWUF4ZF6LLA13069
ZHWUF4ZF1LLA13206
ZHWUF4ZF4LLA13135
ZHWUF4ZF5LLA13029

Warning: before starting with the repair, log to the Warranty portal and check through VIN Info:

- The vehicle is effectively involved by these bulletin instructions; some cars may not be included even when they are in the VIN range.
- The procedure identified by a letter (e.g. A, B or C....etc. whose differences are explained below in this bulletin), taking care to order and use the parts corresponding to the assigned procedure.

Example
**NOTE:**

Procedure A will be available only when the instructions require to carry out a preliminary control to determine whether or not a vehicle needs to be updated.

Information to the field.

As a result of continuous product monitoring, Automobili Lamborghini S.p.A requests the dealers to replace the instrument scoop cover due to a wrong configuration release.

Field solution

Replace the instrument scoop cover as per the herein procedure.

Spare parts.

Order the following part number which is connected to the operation:

- **Operation B:** instrument scoop cover replacement

P/N	Description	Q
4T0858189C	Instrument scoop cover	1

Replaced parts management.

Store properly and tagged the parts replaced with bar code form for their identification during Area Manager visits.

Labour time.

- Operation B : 1,5 hours

Warranty Claim instructions

To claim the reimbursement log into the warranty system management on the Lamborghini Portal and consults the



manual “W.Claim “ available on the portal for the download .

Select the desired campaign and go on with the claim insertion, read carefully the windows message content and choose the option button corresponding to the operation performed .

On the base of the chosen option the reimbursement will be:

- **OPTION B:** Instrument scoop cover replacement
 manpower: 1,5 hours
 spare parts: 4T0858189C



ATTENTION!

Attach all documents produced during the vehicle visit that show evidence of the work performed such as repair order, software protocols or acquisitions...etc.; the lack of one or more of those, may deny the reimbursement.

Remember to fill all data in the section “Service and Recall Campaign” in the Warranty booklet of the vehicle as shown below.

Necessary tools/material.

P/N	Description	Q
n/a	n/a	n/a



Work instructions

1. Carefully follow the instructions below to replace the Instrument scoop cover.

To perform this operation, follow the instructions given in the repair manual at the following path:

08 Body → 57 Interior equipment → Upper liner on the instrument cluster cover → Disassembly/Assembly



IMPORTANT:

The documents which must be provided with the warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol.*

Failure to follow these procedures could lead to the request being rejected.