

Technical Service Bulletin

Topic	New Continental GT - Rear lamps, Boot lid and Rear bumper moulding
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2051495/2
Level	GH
Status	Released for publishing
Release date	Aug 21, 2019

New customer code

Object of complaint	Complaint type	Position
lighting, signaling -> exterior lighting -> rear lamps -> body/rear lid tail lamp change-over	functionality -> no function	> no instruction <
lighting, signaling -> exterior lights	dimensional accuracy	
lighting, signaling -> exterior lighting	dimensional accuracy	

Vehicle data

New Continental GT

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*

Documents

Document name
master.xml

■

Condition

Rear Lamps, Boot lid and Rear bumper moulding profile/alignment

Technical Background

Due to the design and fitment of the rear lights in relation to the boot lid and rear bumper moulding ensure the instructions within the Measure section of this TPI are followed

Production Solution

Not applicable

Service

□

After the replacement/removal of the Rear lamps, Boot lid or rear bumper moulding it is imperative that the instructions within Elsa Pro are followed to ensure the gap and profile between the afore mentioned components are within the approved specification, these instructions can be found in Elsa Pro in the locations shown below:

Rep.Gr 94 - Rear lamps - To remove and fit

Rep.Gr 55 - Boot lid and fittings - Boot lid - To set

Rep.Gr 63 – Rear bumper moulding - To remove and fit