

Technical Service Bulletin

Topic	New Continental GT - Mood lighting
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2051511/3
Level	EH
Status	Released for publishing
Release date	Aug 21, 2019

New customer code

Object of complaint	Complaint type	Position
lighting, signaling -> interior lighting -> backlighting	functionality -> irregular	
lighting, signaling -> interior lighting -> backlighting	functionality -> no function	
lighting, signaling -> interior lights -> door light strip	component, automotive fluids -> damaged	
lighting, signaling -> interior lights -> fluorescent tube	component, automotive fluids -> damaged	
lighting, signaling -> interior lights	functionality	

Vehicle data

New Continental GT

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*

Documents

Document name
master.xml



Condition

Mood lighting strip fixed on one colour regardless of which colour scheme is selected or not illuminated at all

Technical Background

Refer to the Measure section of this TPI

Production Solution

Not Applicable

Service

- 1) Check the integrity of the applicable mood light strip electrical circuit - Refer to Elsa pro wiring diagrams
- 2) Check the mood light strip electrical connections are correctly made to the affected mood lighting strips, if not connected correctly refit and confirm connection and retest
- 3) Should the connector or mood light strip be found to be damaged, replace the mood lighting strip Refer to Elsa pro – Rep.Gr 96 - Mood lighting strips - To remove and fit