



Volkswagen



2019 Atlas

Engine	Part	Part Number	Quantity
2.0L Turbo: DCGA	Oil Filter	06K 115 562L	1
	VW 504 00 Use synthetic oil SAE 0W-30	N/A	5.7L (6.0qt)
	Drain Plug Gasket	N 908 130 03	1
	Air Filter	3QF 129 620	1

Engine	Part	Part Number	Quantity
3.6L: CDVC	Oil Filter	03H 115 562	1
	VW 504 00 Use synthetic oil SAE 0W-30	N/A	5.5L (5.8qt)
	Drain Plug Gasket	N 908 132 02	1
	Air Filter	3QF 129 620	1

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Pollen Filter	520-819-644A	1
	Front Wiper Blades – Set	3CN-998-002	1
	Rear Wiper Blade	3CN-955-427	1
	Battery (Amp. Req. Vary)	000 915 105*	1

*VIN Required

2019	Engine Code		Torque Spec
Oil drain plug Torque	2.0L	DCGA	30 Nm
	3.6L	CDVC	
Wheel hub bolt Torque	2.0L	DCGA	120 Nm
	3.6L	CDVC	

Revised 9/24/2019

Resetting the oil service reminder


If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:


1. Switch off the ignition.
2. Press and hold the **0.0/SET** button in the instrument cluster.
3. Switch on the ignition.
4. Release the **0.0/SET** button.
5. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

1. Switch off the ignition.
2. Switch on the emergency flashers.
3. Press and hold the **0.0/SET** button in the instrument cluster.
4. Switch on the ignition.
5. Release the **0.0/SET** button.
6. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.
7. Switch off the emergency flashers.

 Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

 The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.