



Countries:	CANADA, UNITED STATES	Document ID:	IK1201389
Availability:	ISIS, Bus ISIS, FleetISIS, Body Builder, IsSIR	Revision:	1
Major System:	ENGINES	Created:	8/21/2017
Current Language:	English	Last Modified:	9/11/2019
Other Languages:	NONE	Author:	Michael Sokolowski
Viewed:	947		

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 5	Not Helpful 4
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: Cummins ISB Fan Drive Belt Chirp

Applies To: Cummins ISB, Cummins B6.7 IC Bus

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

09/11/2019 - Article was retired incorrectly. Re-published article.
08/28/2017 - Initial Article Release

DESCRIPTION

This document will guide the user to Cummins TSB information regarding fan belt noise concerns

SYMPTOM(s)

Diagnostic Trouble Code(s) & Dashboard Indicator Light(s):
N/A

Customer Observations or Concerns:

- Fan drive belt noise (chirp or squeal)
- Premature wear of fan drive belt

SPECIAL TOOL(s) / SOFTWARE

N/A

SERVICE PARTS INFORMATION

--	--	--	--

Kit Description	Part Number	Quantity Required	Notes
BELT FAN*V-RIBBED 8PK 82.68	1842467C1	1	

DIAGNOSTIC STEP(s)

See Cummins TSB
 Quickservice Link: [TSB170046](#)

REPAIR STEP(s)

See Cummins TSB
 Quickservice Link: [TSB170046](#)

WARRANTY INFORMATION

Warranty Claim Coding:
 Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.

Standard Repair Time(s):
 Refer to the [SRT Manual](#) for Repair Times
 Also, see Cummins SRT

OTHER RESOURCES

- [Cummins Quickservice Home](#)
- [Master Service Information Site](#)

Hide Details
Feedback Information

Viewed: 946
Helpful: 5
Not Helpful: 4
No Feedback Found