

# Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

## SSM 74560 - Gesture Roof Blind feature deletion at 20MY onwards

**Models :** Range Rover / L405  
Range Rover Sport / L494

**Engineer :** Richard Attwood

**Date Last :** 01 OCT 2019 07:25:02

**Updated :**

**Content :Issue:** The feature 'Gesture Roof Blind' is no longer available for 20MY onwards Range Rover and Range Rover Sport.

**Cause:** Feature change at 20MY.  
RR 20MY start VIN - LG567624  
RR Sport 20MY start VIN - LW876107

**Action:** No action required as the feature is no longer fitted. This SSM is an advisory communication only. Please do not attempt diagnosis or component fitment of this obsolete feature.

**Note:** You may observe the harness that connected to the gesture roof blind sensor remains present and is taped back to the roof harness. This is normal to prevent any Noise Vibration Harshness concerns developing. The description and operation section of the TOPIx Workshop Manual will be updated shortly for 20MY onwards Range Rover and Range Rover Sport to reflect removal of the feature.

**Version :** 2