

2018 Golf, GTI, Golf R, SportWagen, & Alltrack



Engine	Part	Part Number	Quantity
	Oil Filter	06K 115 562	1
1.8L Turbo: CXBA	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
		06L 103 801	1
	Air Filter	5QM 129 620	1

Engine	Part	Part Number	Quantity
	Oil Filter	06K 115 562	1
2.0L Turbo GTI: CXCB	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
2.02 74.30 07.11 07.02	Drain Plug W/Gasket	06L 103 801	1
	Air Filter	5QM 129 620	1

Engine	Part	Part Number	Quantity
	Oil Filter	06L 115 562	1
2.0L Turbo (Golf R):	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
CYFB, DJJA	Drain Plug W/Gasket	06L 103 801	1
	Air Filter	5Q0 129 620 B	1

Miscellaneous	Part	Part Number	Quantity
	Pollen Filter w/o electronic HVAC Regulation (20K Only)	5Q0 819 644 A	1
	Pollen Filter with electronic HVAC Regulation (20K Only)	5Q0 819 669	1
	Front Set Wipers	5GM 998 002	1
Miscellaneous	Rear Wiper Blade (Golf)	5GM 955 427 A	1
	Rear Wiper Blade (GTI)	5GM 955 427	1
	Rear Wiper Blade (Golf R)	5G6 955 427 A	1
	Battery (Amp. Req. Vary)	000 915 105*	1
	Battery (Amp. Req. Vary)	5KO 915 105*	1
	Battery (Amp. Req. Vary)	5GM 915 105*	1

*VIN Required



2018 Golf, GTI, Golf R, SportWagen, & Alltrack



2018	Engine Code		Torque Spec
	1.8L	СХВА	
Oil drain plug Torque	2.0L	СХСВ	30 Nm
	2.0L	CYFB,DJJA (Golf R)	
	1.8L	СХВА	
Wheel hub bolt Torque	2.0L	СХСВ	120 Nm
	2.0L	CYFB,DJJA (Golf R)	

Revised 10/2/2019

2018 Golf, GTI, Golf R & Alltrack Service Reminder Reset

Resetting the service reminder display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

- Switch off the ignition.
- Press and hold the [0.0] button in the instrument cluster.
- Switch on the ignition.
- Release the 0.0 button.
- One after the other, the following messages appear in the display:

Reset oil change interval?

Reset inspection interval?

• When you see the message for the interval you want to reset (either oil change or inspection), confirm the request by pressing the $\boxed{0.0}$ button in the instrument cluster. A confirmation message appears in the display when the service reminder has been reset.



Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.