



Bulletin No.: PIT5706

Published date: N/A

# Preliminary Information

## PIT5706 Adaptive Cruise Control Inoperative and Lane Keep Assist System Unavailable

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2020	All	All	All	All
Chevrolet	Traverse	2020	All	All	All	All

Involved Region or Country	North America
Condition	<p>Some customers may comment one of the following messages is displayed on the driver information center (DIC):</p> <ol style="list-style-type: none"> <li>1. Adaptive Cruise Temporarily Unavailable or ACC TEMP UNAVAILABLE</li> <li>2. Lane Keeping Assist System Unavailable or LKA UNAVAILABLE</li> <li>3. Service Driver Assist System message</li> </ol>
Cause	This condition may be caused by a software anomaly.

### Correction:

Perform a yaw rate sensor relearn.

### Version History

Version	<b>1</b>
Modified	09/05/2019 - Created on



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.