



Bulletin No.: PIT5712
Published date: 09/26/2019

Preliminary Information

PIT5712 Illuminated Sill Plate will not Light up, Inoperative

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer	2019	All	All	All	All

Involved Region or Country	North America
Condition	A customer may complain that the illuminate's sill plate will not light up
Cause	Distance between rocker sill that sill plate is mounted to and bottom of door is too great for sensor

Correction:

Engineering is aware of the issue and is currently working on a repair. Do not replace the part. This bulletin will be updated upon repair validation.

Version History

Version	1
Modified	09/26/2019 - Created on

