


Latest Vehicle Concern Fixes



Range Rover Sport Stalling in Lower RPM Range and can be Restarted	2019 Range Rover Sport equipped with AJ20P6
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• The vehicle stalled when slowing down.• The engine shut down, everything else stayed on. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• The condition may be experienced at various speeds with low engine RPM.• Entry conditions are more likely to be met in warmer ambient conditions.• The vehicle can be restarted on the next ignition cycle. <p><u>Status:</u></p> <ul style="list-style-type: none">• A revised PCM calibration will be released to resolve this condition and additional robustness improvements.• Current ETA is CW39.• If you receive this customer complaint of stalling and are unable to identify a root cause during primary and secondary diagnosis, raise a TA.	 A detailed photograph of the AJ20P6 engine, showing various components like the intake manifold, belts, and pulleys.

