

Subject

Wi-Fi Intermittently Inoperative

Market

USA

Service Category

Audio/Visual/Telematics

Section

Cellular Communication

Applicability

2020 Tundra and Sequoia

APPLICABLE VEHICLES

2020

Tundra

2020

Sequoia

CONDITION

Some 2020 model year Tundra and Sequoia vehicles may experience a B15DB or intermittent Wi-Fi inoperative (Wi-Fi icon greyed out). To simplify the diagnosis of the inoperative Wi-Fi, refer to the procedure below to prevent unnecessary parts replacement.

RECOMMENDATIONS

To restore the Wi-Fi operation perform one of the following:

- Turn the vehicle off for 3 hours minimum
- Remove the DCM fuse for 10 minutes
- Disconnect the battery for 10 minutes

LINK REFERENCES

This Tech Tip does not contain any link references