



Mitsubishi Motors North America, Inc.

6400 Katella Avenue
Cypress, CA 90630
Telephone: 714-372-6000
www.mitsubishicars.com

AFFECTED VEHICLES
MODEL: 2012 i-MiEV

Date: September 2019

Dear Name,

Mitsubishi Motors North America Inc. has determined that due to potential low durability of the capacitors on the circuit boards in the On-Board Charger (OBC), the capacitors may short and cause the high voltage fuse in the Motor Control Units (MCU) to blow. As a result, the drive battery may not be charged by regular charging and the 12V battery may not be charged. When this occurs, the power unit and 12V battery warning lights will turn on.

To ensure your continued satisfaction with your vehicle, Mitsubishi is extending the warranty for the OBC on your vehicle to **10 years / unlimited miles**.

If you have already had the OBC replaced on your vehicle and have paid for the repair, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement consideration:

Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

Please keep a copy of this notification with your vehicle's warranty book for future reference. If you have any questions, please contact us:

Mitsubishi Customer Relations Department • P.O. Box 6400 Cypress, CA 90630-0064
Phone 1-888-648-7820 Hours: Monday – Friday 7 a.m. – 4 p.m. Pacific Time

Sincerely,

Mitsubishi Motors North America, Inc.

TSB-19-54-016