

## Latest Vehicle Concern Fixes



<b>Pop Noise from Audio Output</b>	17 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• Popping sound or crackling noise from the audio system while in use.</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• Under investigation, could be IMC or AAM software</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• Primarily reported on Range Rover Velar or Land Rover Discovery</li><li>• Issue containment has been verified with IMC software 19B, scheduled for Pathfinder release on September 18<sup>th</sup> 2019.</li></ul>	

