

NUMBER: 02-004-19

GROUP: 02 - Front Suspension

DATE: August 17, 2019

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Service Bulletin is also being released as Rapid Response Transmittal (RRT) 19-059, dated August 17, 2019. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

SUBJECT:

Steering Wheel Off Center

OVERVIEW:

This bulletin involves centering the steering wheel.

MODELS:

2019 (WD)

Dodge Durango

NOTE: This bulletin applies to vehicles within the following markets/countries: North America and EMEA.

NOTE: This bulletin applies to vehicles built on or after March 31, 2019 (MDH 0331XX) and on or before July 22, 2019 (MDH 0722XX).

SYMPTOM/CONDITION:

The customer may describe:

The steering wheel is off center.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. **This RRT only applies** to vehicles on the RRT VIN list.

- 1. Test drive the vehicle "as is" before making any changes to confirm the steering wheel is off center. Refer to DealerCONNECT> Service Library for the published Service Bulletin specific to diagnosing a "Steering Wheel Not Centered" condition.
- 2. Was the steering wheel found to be off center?
 - YES>>> Continue with Step 1 of the Repair Procedure.
 - NO>>> This Bulletin has been completed. Use inspect LOP (02-00-02-9K) to close the active RRT.

02-004-19 -2-

REPAIR PROCEDURE:

1. Check and adjust toe as necessary. Refer to the detailed service procedure for setting "Toe" available in DealerCONNECT> Service Library under: Service Info 02 Front Suspension> Wheel Alignment> Standard Procedure> Wheel Alignment> Toe Adjustment.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
02-00-02-9K	Road Test Vehicle to Verify Steering Wheel Off Center Condition (1 - Semi-Skilled)	4 - Chassis Systems	0.2 Hrs.
02-00-02-9L	Road Test Vehicle and Perform Front Wheel Toe Adjustment (1 - Semi-Skilled)	4 - Chassis Systems	0.7 Hrs.

FAILURE CODE:

ZZ	Service Action	
----	----------------	--