



Service Bulletin

Bulletin No.: 17-NA-194

Date: September, 2019

INFORMATION

Subject: Information on Charge Air System Leaks, Malfunction Indicator Lamp (MIL) Illuminated - DTCs P0101, P0263, P0266, P0269, P0272, P0275, P0278, P0281, P0284, P0299, P0712, P11CC, P11DC, P2002, P2459, P2463, P2627, P200C, P200E, P20EE, P22B6 and/or P2A00 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2016	2020			Diesel (RPO LWN)	
	Express						
GMC	Canyon						
	Savana						

Involved Region or Country	North America, Israel, Middle East
Condition	<p>Some customers may comment that the MIL is illuminated. The technician may find one or more of the following DTCs set:</p> <ul style="list-style-type: none"> • P0101 • P0263 • P0266 • P0269 • P0272 • P0275 • P0278 • P0281 • P0284 • P0299 • P0712 • P11CC • P11DC • P2002 • P2459 • P2463 • P2627 • P200C • P200E • P20EE • P22B6 • P2A00
Cause	This condition may be caused by an induction system leak.
Information	To locate a leak, it is recommended to perform a Charge Air Cooler Diagnosis (Full System Air Leak Test).

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under warranty, use the appropriate labor operation for the repair performed. Use OLH for the time required to perform the Full System Air Leak Test.

Version	5
Modified	Revised August 30, 2017 — Added 2018 Model Year. Revised July 24, 2018 – Added 2019 Model Year. Revised September 12, 2018 - Add Warranty Information section. Revised September 18, 2019 – Add 2020 Model Year.

