



Condition

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2018-2019	All	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2056713/1	10/18/2019	96-19-01T	Original publication.

Technical Background

All Wheel Drive Function not working. Driving Profile Selection Control Head -E881- Inoperative.

Service

1. Connect a Scan Tool.
2. Go to Special Functions.
3. Go to SVM Software Version Management, see figure 1.

Perform the following procedures:

- Control module software configuration and FES function clearing system.
- Select Re-create Function for AW 19 (-J533- Data Bus on Board Diagnostic Interface).
- Once procedures are complete, recheck All Wheel Drive operation.




Figure 1.



Additional Information

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.