

SS: 1034533 TBB Headlamp Buzzer Feature availability

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue of for unit after 2016 with certain application the headlamp Buzzer alarm was removed. Engineering has released a New feature that can be applied to units if elect.

Applicable Vehicles

C2 units built after 2016

Issue

Headlamps on with key off will not alert driver to turn the lights off

Solution:

Apply feature 26-02090-004 with Diagnostic link or Service Link capability