

# SS 1034499 WST RX Modules Failing

---

## Applicable Vehicles:

All 4700, 4800, 4900, & 6900 Models

## Concern:

RX Modules fail and are unable to send proper signals (See Below for Example).



## Cause:

In some cases RX Modules are mounted on an uneven surface causing a twist in the module which leads to an internal failure

