

WKA2 Workshop campaign - Replacing exhaust system holders

Version 2

Update 4/15/19

The TI and VIN list are now attached to this post. Repairs can be completed on all affected VINs.

English (GB)

> [Overview](#)

WKA2 Workshop campaign - Replacing exhaust system holders

Overview

Exhaust gas pulsations occur in the front silencer area during overrun at an engine speed of approx. 1,100 rpm.

This can cause vibrations in the exhaust system, resulting in noises.

To prevent this from happening and to make the system more robust, the exhaust system brackets must be replaced by technically optimised brackets.

Within the market area for which you are responsible, please arrange for this measure to be carried out the next time the affected vehicles come into the workshop.

Model type	Cayenne S (9YA)
Model year	2018 to 2019
Manufacturing period	between 09.14.2017 and 10.09.2018
Number	5

Further Information

If you have any questions please email Mitchell.grasser@porsche.us

[9YA 2 4-19 WKA2 Replacing Exhaust System](#)

[Holders.pdf](#)

117.3 KB

(87 views)

[WKA2_VIN_list_USA.xlsx](#)

11.6 KB

(57 views)

Created by [Mitchell Grasser](#) on Apr 3, 2019 12:31 AM. Last modified by [Mitchell Grasser](#) on Apr 15, 2019 7:50 PM.

Categories: Workshop Campaigns, Cayenne

Tags : [workshop](#), [cayenne s](#), [year k](#), [wka2](#)

1314 Views [Report Abuse](#)

Content and Topics

Your Groups >

Your Content >

Your Places >

Personal

Edit Profile >

Change Password >

Manage

Admin Console >

PPN Administration >

Create

Discussion >

Files >

Document >

Collaboration >

Document

Blog Post >

Poll >

Message >

Event >

Photo Album >

Idea >

Space >

© 2019 Dr. Ing. h.c. F. Porsche AG. [Legal notice](#). [Copyright](#). [Terms of use](#). [Privacy Policy](#). [Cookie Policy](#). [011](#)