

WJ82 Campaign - Re-coding gateway control unit (MY 2017 Panamera)

Version 6

English (US)

- > Overview
- > Required software
- > Warranty processing
 - > Scope:

WJ82 Campaign - Re-coding gateway control unit

Overview

Due to a software error, the sports exhaust system can remain activated after switching the ignition on and off again although it is shown as inactive in the Vehicle menu.

To implement these improvements in the affected vehicles, the Gateway control unit must be re-coded.

Model type	Panamera (971)
Model year	2017
Equipment:	Sports exhaust system (I-no. OP8 or OP9) with Sport Chrono package (I-no. QR5)
Number	221

VIN List of affected vehicles is attached below

Required software

PIWIS Tester 3 test software version	37.800.020 (or higher)
---	------------------------

Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope:

Damage code	WJ82 66 000
Repair code	1
Working time	46 TU

If any questions arise, please feel free to contact me directly.

Ryan Cooney

Senior Regulatory Affairs Consultant

ryan.cooney@porsche.us

[971 9 152-18 WJ82 Recoding Gateway Control](#)

[Unit.pdf](#)

295.6 KB

(43 views)

[WJ82 VIN List.xlsx](#)

19.8 KB

(10 views)

Created by [Ryan Cooney](#) on Jun 5, 2019 12:00 AM. Last modified by [Ryan Cooney](#) on Aug 15, 2019 4:36 PM.

Categories: Panamera

Tags : [panamera](#), [971](#), [workshop campaign](#)

574 Views

Content and Topics

Personal

Manage

Create

Your Groups >

Edit Profile >

Admin Console >

Discussion >

Your Content >

Change Password >

PPN Administration >

Files >

Your Places >

Document >

Collaboration >

Document

Blog Post >

Poll >

Message >

Event >

Photo Album >

Idea >

© 2019 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. 011