

WH75 Workshop Campaign "Replacing airbag control unit"

Version 2

English (US)

- > Overview
- > Parts required
 - > Ordering required parts
- > Required software
- > Warranty processing
 - > Scope 1: Replacing airbag control unit
- > Further information

WH75 Workshop campaign "Replacing airbag control unit"

Overview

An airbag control unit that does not meet the required specifications was installed on the affected vehicles.

As a result, when the airbag control unit is exposed to electromagnetic interference, it can incorrectly send an accident message to the Porsche Vehicle Tracking System (PVTS) control unit. The PVTS control unit then automatically sends an emergency call with location and vehicle data. An emergency plan is activated and the emergency service is informed.

To prevent this from happening, the airbag control unit must be replaced by a modified airbag control unit.

Model type	911 GT3 (991) / 911 GT3 RS (991)
Model year	2018 - 2019
Vehicle specifications	Porsche Vehicle Tracking System Plus (I-no. 712) Porsche Vehicle Tracking System Plus with remote keypad (I-no. 710) VTS preparation and Porsche Car Connect (I-no. 7G9)
Number	1719

Parts required

Part No.	Designation	Quantity/vehicle	Parts return request*
00004399037	Airbag control unit	1 ea.	No
99907001502	Cap nut	3 ea.	No

* The parts must be stored until such a time as the **related warranty or campaign claim has been credited** in WWS. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche as usual.

Ordering required parts

PCNA will auto-allocate 80% of parts for this campaign to your dealer based on UIO, which will arrive in calendar week 37. Additional parts beyond the 80% auto-allocation can be ordered as required without PTEC or email. Additional updates, including parts status, will be added to this campaign page when available.

Required software

PIWIS Tester 3 test software version	37.600.030 (or higher)
---	------------------------

Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1: Replacing airbag control unit

Damage code	WH75 66 000 2
Working time	177 TU

Further information

Work instruction	TI No. 98/18, Group 6, Service, WH75
Vehicle list and allocation	See Attached VIN List
Technical Information	PIWIS

For further information, please contact:

Ryan Cooney
Regulatory Affairs
ryan.cooney@porsche.us

[991 6 98-18 WH75 Replacing Airbag Control](#)

[Unit.pdf](#)

57.3 KB

(38 views)

[WH75 VIN List.xlsx](#)

35.9 KB

(42 views)

Created by [Ryan Cooney](#) on Sep 4, 2019 2:03 PM. Last modified by [Ryan Cooney](#) on Sep 6, 2019 10:10 PM.

Content and Topics

Personal

Manage

Create

Your Groups >

Edit Profile >

Admin Console >

Discussion >

Your Content >

Change Password >

PPN Administration >

Files >

Your Places >

Document >

Collaboration >

Document

Blog Post >

Poll >

Message >

Event >

Photo Album >

Idea >

Space >

© 2019 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [011](#)