WKJ4 Stop Delivery - Replacing rear axle differential

Version 4

English (US)



- **>** Update 10/29/2019:
- > Vehicle blocking
- Overview
- > Vehicle usage
- Workshop instructions and remedial measures

WKJ4 Stop Delivery - Replacing rear axle differential

Update 10/29/2019:

Please note that the required rear axle differentials are not available in sufficient quantity. We will publish the technical information as soon as the parts can be ordered.

Vehicle blocking

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Therefore, please carry out following Stop Delivery, immediately.

Overview

There is a possibility that the collar nut on the pinion shaft of the rear axle differential may loosen on the affected vehicles. This can create noise and may lead to a damaged rear axle differential.

To avoid this, the rear axle differential of the affected vehicles must be replaced.

Cayenne (9YA, 9YB)
2020
Between 08/28/2019 and 09/02/2019
31

Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain.

Further use is not permitted. Test drives should not be performed.

Workshop instructions and remedial measures

Will be communicated once available (approx. cw 42).

WKJ4 VIN List.xlsx

8.9 KB

(258 views)

Created by Ryan Cooney on Oct 10, 2019 2:32 PM. Last modified by Ryan Cooney on Oct 29, 2019 7:26 PM.

Categories: Workshop Campaigns, Cayenne, Stop Sale Tags : cayenne, stop delivery, year_k, wkj4 1058 Views

Report Abuse

Content and Topic	CS	Personal	Manage	Cre	eate	
Your Groups	>	Edit Profile >	Admin Console >		Discussion	>
Your Content	>	Change Password >	PPN Administration>		Files	>
Your Places	>				Document	>
				Doc	Collaboration ument)
					Blog Post	>
					Poll	>
					Message	>
					Event	>
					Photo Album	>
					Idea	>
					Space	>
					Group	>

© 2019 Dr. Ing. h.c. F. Porsche AG. <u>Legal</u>

notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. 009