

SSM 48232 - 2019 Continental - Inoperative Navigation, Compass Only Points North, And/Or The Clock Cannot Be Set Automatically - Built On Or Before 11-Feb-2019

Some 2019 Continental vehicles built on or before 11-Feb-2019 may experience a concern where the compass only points north, the clock cannot be set using the "Reset Clock to GPS Time" feature and/or the navigation will be inoperative. This may be due to a fault with the global positioning system (GPS) antenna, a fault with the communication of the wheel speed and wheel rotation direction information, a fault with the GPS coaxial cable, or a fault with the SYNC module (APIM). Follow normal Workshop Manual (WSM) diagnosis to correct this condition.