

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

**SSM 74588 - 16MY Onward vehicles equipped with AJ126 S/C Petrol
Check Engine MIL or Noise from HP Pump**

Models : Discovery / L462

Discovery 4 / L319

Range Rover / L405

Range Rover Sport /
L494

Range Rover Velar /
L560

Engineer Priestner Matt

Name :

Last 16 OCT 2019 14:52:02

Modified :

Category : Driveability

Symptom : 698298 Malfunction Indicator Lamp

Content : Issue:

Vehicles equipped with an AJ126 supercharged V6 engine are experiencing noise from the HP fuel pumps and/or a Check Engine MIL illuminated with one of the following DTCs stored in the PCM.

P228F-85

P025C-11

P0251-13

P064A-38

P0256-13

Cause:

Under Investigation.

Action:

If a noise is identified from the HP fuel pump or one of the DTCs listed above is present, raise a TA and include a video or sound file of the noise complaint (if applicable) and a session file. If only the Check Engine MIL is present without a noise complaint and none of the DTCs listed are stored, complete diagnostics and repair as outlined in the TOPIx workshop manual section 100-00: General Information > Diagnostic Trouble Code Index DTC: V6 S/C 3.0L Petrol.

