


Latest Vehicle Concern Fixes



No Audio Output or Loss of Audio	19 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customer states there is no audio output from the speakers on all sources <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• IMC hardware failure <p><u>Status:</u></p> <ul style="list-style-type: none">• Primarily reported on 19MY vehicles• LR – SSM 74491 has been released on July 26th 2019• JAG – SSM 74490 has been released on July 26th 2019• Part stock has been confirmed clean.• Permanent Corrective Action PCA to be completed by Dec 20th 2019.	 Two technical line drawings of the InControl Touch Pro audio system unit. The drawing on the left shows the front view of the unit, highlighting two circular speaker drivers. The drawing on the right shows the rear view of the unit, displaying various electrical connectors and ports.

