

## Latest Vehicle Concern Fixes



Forward Alert Message On The Instrument Cluster	18MY Onwards Range Rover / RRS 19MY Onwards Discovery
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• Customer may state the adaptive speed control is inoperative</li><li>• There is a Forward Alert message on the Instrument Cluster (IC)</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• Adaptive speed control bracket is potentially bent/damaged due to an impact to the front bumper.</li><li>• DTC C1A67-78 and/or C1A67-54 may be found during diagnosis.</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• SSM 74547 is published</li><li>• Upon diagnosis if the bracket is found to be bent and there is no visible damage to the front bumper.</li><li>• Please submit an EPQR and provide pictures of the bracket and the bumper showing there is no damage.</li></ul>	

