



Preliminary Information

PIT5706A Adaptive Cruise Control Inoperative and Lane Keep Assist System Unavailable

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2020	All	All	All	All
Chevrolet	Traverse	2020	All	All	All	All

Involved Region or Country	North America
Condition	<p>Some customers may comment one of the following messages is displayed on the driver information center (DIC):</p> <ol style="list-style-type: none"> 1. Adaptive Cruise Temporarily Unavailable or ACC TEMP UNAVAILABLE 2. Lane Keeping Assist System Unavailable or LKA UNAVAILABLE 3. Service Driver Assist System message
Cause	This condition may be caused by a software anomaly .

Correction:

Perform a yaw rate sensor relearn.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2886518	Vehicle Yaw Sensor Learn	0.3
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	2
Modified	09/05/2019 - Created 10/08/2019 to add a labor operation for tracking.



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.