



Bulletin No.: PIC6356A
Published date: 10/22/2019

Preliminary Information

PIC6356A Normal Characteristic - Fuel Filler Door Does Not Lock Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Regal	2018 - 2019	ALL	ALL	All	All

Involved Region or Country	North America
Condition	<p>A customer may comment that their fuel door does not lock. A vehicle enhancement was put into place which has eliminated the locking fuel filler door resulting in the door no longer locking.</p> <p>2019 Buick Regals starting with VIN K1038582 were not built with the locking fuel filler door feature.</p> <p>If the fuel filler door is being replaced on 2018 and 2019 Regals, prior to the VIN break, service parts will no longer have the locking feature.</p>

Correction:

Do not replace any parts, the fuel door is operating as designed.

Note: This PI may be converted into a bulletin when new information is available.

Version History

Version	2
Modified	03/13/2019 - Created on. 10/22/2019 - Updated MYs and service part information.

