

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: A/C BLOWS WARM AIR DUE TO REFRIGERANT LEAK FROM CONDENSER	Bulletin No.: 07-001/19
	Last Issued: 11/06/2019

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below: The changes are noted in Red.

Previously issued TSBs:	Date issued:
07-001/19	01/11/2019 and 09/10/2019
07-001/18	01/17/2018 and 04/19/2018
07-001/17	01/06/2017 and 02/15/2017

APPLICABLE MODEL(S)/VINS

2016-2017 CX-3 vehicles with VINs lower than JM1 DK ***** 158284 (produced before October 21, 2016)
2016-2017 CX-3 Canada vehicles with VINs lower than JM1 DK ***** 158210 (produced before October 21, 2016)

DESCRIPTION

Be advised that TSB 07-001/19 is no longer valid and has been superseded to "SSPB8 - 2016-2017 CX-3 A/C CONDENSER WARRANTY EXTENSION".

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.