## **Service Alert**

Mazda North American Operations Irvine, CA 92618-2922



#### Subject:

# MAZDA CONNECT REBOOTS WHILE DRIVING OR SIRIUS XM SATELLITE RADIO FUNCTION NOT AVAILABLE

Service Alert No.: SA-047/19

Last Issued: 11/06/2019

#### APPLICABLE MODEL(S)/VINS

2019-2020 Mazda6 2019-2020 CX-3 2019-2020 CX-5 2019-2020 CX-9 2019 MX-5

### **DESCRIPTION**

Some customers may have one or more of the following complaints:

- Infotainment system reboots at times
- SiriusXM function grayed out
- SiriusXM stops playing
- No sound from SiriusXM but other sources work
- SiriusXM system recovers after ignition OFF-ON


Do not perform any repairs at this time. Mazda is aware of the concerns and is working on a repair. This service information will be updated when a repair is available.

NOTE: An interim solution is available for the SiriusXM concerns. See details below:

**Example:** 

Page 1 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing.




Page 2 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing.

#### SiriusXM Interim Solution:

- 1. Install the SiriusXM App on the customers device.
- 2. The customer can stream music on the SiriusXM App temporarily until the final repair is available.

NOTE: Customer device, data service is used to stream music on the SiriusXM App.



#### Page 3 of 3