

Service Bulletin

INFORMATION

Subject: Corrosion and/or White Powder Build Up On the A/C Lines in the Engine Compartment

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Colorado (VIN S, VIN T)	2017	2020				
GMC	Canyon						

Involved Region or Country	North America and NA Export vehicles	
Condition	5044650 Some customers may comment on corrosion and/or white powder on the A/C lines in the engine compartment.	

Cause	S06302 This condition may be caused by flux build up during the supplier brazing process of the A/C lines.
Correction	Check and verify that no leaks are found and clean the flux build up using a soft wire brush. Note: DO NOT replace the A/C lines for this condition.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4481918*	Cleaning Off Flux Build Up On the A/C Lines Using a Soft Wire Brush	0.2 hr.
*This is a unique Labor Operation for Bulletin use only.		

Version	4	
	Released April 20, 2018	
Modified	Revised May 10, 2018 – Added Warranty Information.	
Woullied	Revised April 30, 2019 – Added 2019 Model Year	
	Revised October 23, 2019 – Added 2020 Model Year and Updated bulletin.	

