

**Subject: Engineering Information – Fuel Odor, Leak and/or Scraping Noise Heard Under Vehicle While Driving**

*This PI has been revised to end the need for information from the field. Please discard PIE0504.*

| Brand:    | Model:    | Model Year: |      | VIN: |    | Engine:                             | Transmission: |
|-----------|-----------|-------------|------|------|----|-------------------------------------|---------------|
|           |           | from        | to   | from | to |                                     |               |
| Chevrolet | Silverado | 2011        | 2017 | -    | -  | Equipped with 6.0L Engine (RPO L96) | -             |
| GMC       | Sierra    |             |      |      |    |                                     |               |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

|                 |  |
|-----------------|--|
| <b>Version</b>  | 2  |
| <b>Modified</b> | Released February 04, 2019<br>Revised October 08, 2019 – Ended the need for further information from the field |