

Subject: Engineering Information – Power Outside Folding Rearview Mirror Shakes, Clicking and/or Noisy While Folding or Loose Between Mirror Head and Mirror Base

This PI has been revised to end the need for information from the field. Please discard PIE0532.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2019	-	-	-	-
	Silverado 1500	2020	2020				
GMC	Sierra 1500 (New Model)	2019	2019				
	Sierra 1500	2020	2020				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 14, 2019 Revised October 11, 2019 - Ended the need for further information from the field.