



2015 Beetle/Beetle Convertible

Engine	Part	Part Number	Quantity
1.8L Turbo: CPKA, CPRA	Oil Filter	06L115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.7qt)
	Drain Plug Gasket	N-0138157	1
	Air Filter	5C0129620	1

Engine	Part	Part Number	Quantity
2.0L Turbo Diesel: CVCA	Oil Filter	03N115562	1
	VW 507 00 Use synthetic oil SAE-5W-30	N/A	5.5L (5.8qt)
	Drain Plug Gasket	N-90813202	1
	Air Filter	1K0129620D w\PR-0Y2	1
	Air Filter	1K0129620L w/PR-0Y3	1
	Fuel Filter (20K Only)	5Q0127177	1

Engine	Part	Part Number	Quantity
2.0L Turbo: CPLA, CPPA	Oil Filter	06K115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.8qt)
	Drain Plug Gasket	N-0138157	1
	Air Filter	5C0129620	1

2015	Engine Code		Torque Spec	
Oil drain plug Torque	1.8L	CPKA,CPRA	M14 plug	30 Nm
			M24 plug	50 Nm
	2.0L	CPLA, CPPA	M14 plug	30 Nm
			M24 plug	50 Nm
	2.0L TDI CVCA	CVCA	M14 plug	30 Nm
		CVCA	M24 plug	50 Nm
	1.8L	CPKA,CPRA	140 Nm	
Wheel hub bolt Torque	2.0L	CPLA, CPPA		
	2.0L TDI	CVCA		


© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Miscellaneous	Part	Part Number	Quantity
	Pollen Filter	1K0819644B w/PR-9AB	1
	Pollen Filter	1K1819653B w/PR-9AK	1
	Wiper Blades (Left or Right)	5C1955425	1
Miscellaneous	Battery	000915105DEDSP (61AH/330A)	1
	Battery	000915105CCDSP (68AH/380A)	1
	Battery	000915105DGDSP (72AH/380A)	1

Revised 11-7-2019

Resetting the oil change service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:



4. Release the **0.0/SET** button and push the button in the instrument cluster within about

3. Switch on the ignition.

20 seconds.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

Vehicles with Premium display: 1. Switch off the ignition. 2. Switch on the emergency flashers. 3. Press and hold the 0.0/SET button in the instrument cluster. 4. Switch on the ignition. 5. Release the **0.0/SET** button. 6. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel. 7. Switch off the emergency flashers. Vehicles with Basic display: 1. Switch off the ignition. 2. Switch on the emergency flashers. 3. Push the **0.0/SET** button in the instrument cluster and hold down. 4. Switch on the ignition. 5. Release the **0.0/\$ET** button and push the □-/① button in the instrument cluster within about 20 seconds.

6. Switch off the emergency flashers.

Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.