



## 2015 Tiguan

Engine	Part	Part Number	Quantity
2.0L Turbo: CCTA	Oil Filter	06J115403Q	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30, or SAE 0W-40	N/A	4.7L (4.9qt)
	Drain Plug Gasket	See Tech Tip 17-12-02 Elsa Doc #2030603	1
	Air Filter	1K0129620D	1

2015	Engine Code		Torque Spec	
Oil drain plug Torque	2.0L	CCTA	30 Nm	
Wheel hub bolt Torque	2.0L	ССТА	FWD	120
			AWD	140

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Pollen Filter	1K1819653B	1
	Wiper Blades – Set	5N1998002	1
	Battery	000915105DEDSP (61AH/330A)	1
	Battery	000915105DGDSP (72AH/380A)	1

Revised 11/7/2019

### Resetting the oil change service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:

Vehicles with Premium display:		
1.	Switch off the ignition.	
2.	Press and hold the $\boxed{\textbf{0.0/SET}}$ button in the instrument cluster.	
3.	Switch on the ignition.	
4.	Release the <b>0.0/\$ET</b> button.	

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

# Vehicles with Premium display: A confirmation message appears in the display. Confirm request with the OK/RESET in the windshield wiper lever or the OK button on the multi-function steering wheel.

#### Vehicles with Basic display:

- 1. Switch off the ignition.
- 2. Push the **0.0/\$ET** button in the instrument cluster and hold down.
- 3. Switch on the ignition.
- Release the 0.0/SET button and push the □/ ① button in the instrument cluster within about 20 seconds.

#### Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

### Vehicles with Premium display:

- 1. Switch off the ignition.
- 2. Switch on the emergency flashers.
- 3. Press and hold the **0.0/SET** button in the instrument cluster.
- 4. Switch on the ignition.
- 5. Release the 0.0/SET button.
- A confirmation message appears in the display. Confirm request with the <u>OK/RESET</u> in the windshield wiper lever or the <u>OK</u> button on the multi-function steering wheel.
- 7. Switch off the emergency flashers.

#### Vehicles with Basic display:

- 1. Switch off the ignition.
- 2. Switch on the emergency flashers.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

#### **Vehicles with Basic display:**

- 3. Push the **0.0/\$ET** button in the instrument cluster and hold down.
- 4. Switch on the ignition.
- 5. Release the 0.0/\$ET button and push the □/④ button in the instrument cluster within about 20 seconds.
- 6. Switch off the emergency flashers.
- Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.
- The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.