



2012 Beetle/Beetle Convertible

| Engine | Part | Part Number | Quantity |
|---------------------------|---|---|--------------|
| 2.0L Turbo: CCTA, CBFA | Oil Filter | 06J115403Q | 1 |
| | VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30 | N/A | 4.7L (5.0qt) |
| | Drain Plug Gasket | See Tech Tip 17-12-02 Elsa Doc #2030603 | 1 |
| | Air Filter | 1K0129620D | 1 |

| Engine | Part | Part Number | Quantity |
|------------------|---|-------------|--------------|
| | Oil Filter | 06D115562 | 1 |
| 2.5L: CBTA, CBUA | VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30 | N/A | 6.0L (6.3qt) |
| | Drain Plug Gasket | N-90813202 | 1 |
| | Air Filter | 07K129620 | 1 |

| 2012 | Engine Code | | Torque Spec | |
|-----------------------|-------------|------------|-------------|-------|
| Oil drain plug Torque | 2.0L | CCTA, CBFA | M14 plug | 30 Nm |
| | | | M24 plug | 50 Nm |
| | 2.5L | CBTA, CBUA | M14 plug | 30 Nm |
| | | | M24 plug | 50 Nm |
| M/bool bub bolt Towns | 2.0L | CCTA, CBFA | 140 Nm | |
| Wheel hub bolt Torque | 2.5L | CBTA, CBUA | | |

| Miscellaneous | Part | Part Number | Quantity |
|---------------|------------------------------|----------------|----------|
| Miscellaneous | Pollen Filter PR-9AB | 1K0819644B | 1 |
| | Pollen Filter PR-9AK | 1K1819653B | 1 |
| | Wiper Blades (Left or Right) | 5C1955425 | 1 |
| | Battery | 000915105DEDSP | 1 |
| | Battery | 000915105DGDSP | 1 |
| | Battery | | 1 |

Revised 11-11-2019





2012 Beetle/Beetle Convertible

Resetting the service reminder display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

| Vehicles with Premium text message display: |
|---|
| Select the Settings menu. |
| In the Service submenu, select the Reset menu item. |
| Confirm request with OK. |
| |
| Vehicles with Basic text message display: |
| Switch off the ignition. |
| Push 0.0 / SET and hold down. |
| Switch on the ignition. |
| Release the 0.0 / SET button and push the button within about 20 seconds. |
| |

Do **not** reset the service reminder between service intervals; otherwise, incorrect information will be displayed.

The service reminder disappears after a few seconds when the engine is running or the OK button has been pushed.