



Volkswagen



2016 Eos

Engine	Part	Part Number	Quantity
2.0L Turbo: CCTA, CBFA	Oil Filter	06J115403Q	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.7L (4.9qt)
	Drain Plug Gasket	N 0138157	1
	Air Filter	1K0129620D	1
Miscellaneous	Pollen Filter	1K0819644B	1
	Wiper Blades – Set	1Q1998002	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery	000915105*	1

*VIN Required

2016	Engine Code		Torque Spec
<i>Oil drain plug Torque</i>	2.0L	CCTA, CBFA	30 Nm
<i>Wheel hub bolt Torque</i>	2.0L	CCTA, CBFA	120 Nm

Revised 11-5-2019

2016 Eos Service Reminder Reset

Resetting the oil change service reminder


If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:


1. Switch off the ignition.
2. Press and hold the **0.0/SET** button in the instrument cluster.
3. Switch on the ignition.
4. Release the **0.0/SET** button.
5. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

1. Switch off the ignition.
2. Switch on the emergency flashers.
3. Press and hold the **0.0/SET** button in the instrument cluster.
4. Switch on the ignition.
5. Release the **0.0/SET** button.
6. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.
7. Switch off the emergency flashers.

 Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

 The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.