



Volkswagen



2016 Jetta / Jetta GLI

Engine	Part	Part Number	Quantity
2.0L CBPA	Oil Filter	1JM115561BZ	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	3.6L (3.8qt)
	Drain Plug W/Gasket	N 91086801	1
	Air Filter	1F0129620	1

Engine	Part	Part Number	Quantity
1.8L Turbo: CPKA, CPRA	Oil Filter	06K115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.7qt)
	Drain Plug Gasket	N 0138157	1
	Air Filter	5C0129620	1

Engine	Part	Part Number	Quantity
2.0L Turbo GLI: CPLA, CPPA	Oil Filter	06L115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.8qt)
	Drain Plug Gasket	N 0138157	1
	Air Filter	5C0129620	1

Engine	Part	Part Number	Quantity
1.4L Hybrid: CNLA	Oil Filter	04E115561H	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	4.0L (4.2qt)
	Drain Plug + Gasket	N 90288901 + N 0138157	1
	Air Filter	04E129620	1
	Fuel Filter (Every 20K miles)	1K0201051K	1



Volkswagen



2016 Jetta / Jetta GLI

Engine	Part	Part Number	Quantity
2.0L TDI: DELA	Oil Filter	03N115562	1
	VW 507 00 Use synthetic oil SAE 5W-30	N/A	5.5L (5.8qt)
	Drain Plug W/Gasket	N 90813202	1
	Air Filter	1K0129620	1
	Fuel Filter (20K Only)	5Q0127177	1

2016	Engine Code		Torque Spec
Oil drain plug Torque	1.4L	CZTA	30 Nm
	1.4L Hybrid	CNLA	
	1.8L	CPKA,CPRA	
	2.0L	CPLA, CPPA	
	2.0L TDI	DELA	
Wheel hub bolt Torque	1.4L	CZTA	120 Nm
	1.4L Hybrid	CNLA	
	1.8L	CPKA,CPRA	
	2.0L	CPLA, CPPA	
	2.0L TDI	DELA	

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Pollen Filter (20K Only)	1K0819644B	1
	Pollen Filter (20K Only)	1K0819644B	1
	Driver's Wiper Blade (Left)	5C7955425B	1
	Passenger's Wiper Blade (Right)	5C7955426B	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1

*VIN Required

Revised 11-5-2019



Volkswagen



2016 Jetta / Jetta GLI

Resetting the oil change service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:

Vehicles with Premium display:

1. Switch off the ignition.
 2. Press and hold the **0.0/SET** button in the instrument cluster.
 3. Switch on the ignition.
 4. Release the **0.0/SET** button.
 5. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.
-

Vehicles with Basic display:

1. Switch off the ignition.
 2. Push the **0.0/SET** button in the instrument cluster and hold down.
 3. Switch on the ignition.
 4. Release the **0.0/SET** button and push the **☐/⊕** button in the instrument cluster within about 20 seconds.
-

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

Vehicles with Premium display:

1. Switch off the ignition.
 2. Switch on the emergency flashers.
-



Volkswagen





2016 Jetta / Jetta GLI


Vehicles with Premium display:

3. Press and hold the **0.0/SET** button in the instrument cluster.
4. Switch on the ignition.
5. Release the **0.0/SET** button.
6. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.
7. Switch off the emergency flashers.

Vehicles with Basic display:

1. Switch off the ignition.
2. Switch on the emergency flashers.
3. Push the **0.0/SET** button in the instrument cluster and hold down.
4. Switch on the ignition.
5. Release the **0.0/SET** button and push the  button in the instrument cluster within about 20 seconds.
6. Switch off the emergency flashers.

 Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

 The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.