

## GPOP - Issue Review System

**Part Number:** 68418245A\$

**Part Description:** SENSOR, Blind Spot Detection (XAN)

**Issue Description:** For blind spot detection sensor inoperative concerns please verify the following prior to sensor replacement:

- 1) Verify sensor is positioned correctly. Remove rear fascia and ensure that the curved face of the sensor is facing outward towards the fascia; the label should not be visible if installed correctly. Curved face should NOT be facing the chassis.
- 2) Verify that the rear bumper is clear of any obstructions then cycle the ignition.
- 3) The vehicle should be driven on the road and pass/be passed by vehicles on both the left and right sides.

For further assistance, please contact Ben Heckathorn at (248) 444-7815 or Bing Guo at (248) 500-7355.

If no response in 15 minutes, proceed with repair.

~ \_\_\_\_\_ ~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---