GPOP - Issue Review System

Part Number: 68354198A\$

Part Description: MODULE, Air Suspension, [SEB]

Issue For replacement of Air Suspension Control Module (ASCM) due to the following

Description: DTCs, please contact Santiago De La Rosa to aid in root-cause prior to repair at

(248) 635-0819 or santiago.delarosa@fcagroup.com

U0132 (Loss of Comm) U0421 (Implausible Data) C220C (Software Supervision)

C15DE-72 (Exhaust Solenoid Actuator Stuck Open)

If no response in 15 minutes, proceed with repair.

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.