



NUMBER: 18-065-19 REV. A

GROUP: 18 - Vehicle Performance

DATE: October 11, 2019

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 18-065-19, dated August 28, 2019, which should be removed from your files. All revisions are highlighted with **asterisks**** and include updated build date and RRT number.**

This Service Bulletin is also being released as Rapid Response Transmittal (RRT) **19-073**, dated October 11, 2019******. All applicable Sold and Un-Sold RRT VIN's have been loaded. To verify that this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.**

SUBJECT:

Flash: Powertrain Control Module (PCM) Updates - AN-K4MCA-18-20191009

OVERVIEW:

Refer to China Joint Venture (JV) released document ****AN-K4MCA-18-20191009****, for details on this service action.

MODELS:

2019	(K4)	Jeep Cherokee (China)
------	------	-----------------------

NOTE: This bulletin applies to vehicles within the following markets/countries: APAC (China only).

NOTE: This bulletin applies to vehicles built on or after **November 13, 2018 (MDH 1113XX)** and on or before September 19, 2019 (MDH 0919XX)****** equipped with a 2.0L I4 DOHC Direct Injected (DI) Turbo Engine W/ESS (Sales Code EC1).**

Policy:

Information Only