

Subject DTC B15A8 - DCM System Internal Failure		Market USA
Service Category Audio/Visual/Telematics	Section Cellular Communication	
Applicability All Applicable Models		

APPLICABLE VEHICLES

2020	Camry	2020	Corolla Hatchback
2020	Camry HV		

CONDITION

Some 2020 model year Camry, Camry HV and Corolla Hatchback vehicles equipped with a DCM may exhibit a B15A8** DTC in history during PDS. This DTC can be triggered during the manufacturing and /or shipping process and does not indicate a problem with the vehicle. To simplify the diagnosis of this DTC, refer to the procedure below to prevent unnecessary parts replacement.

RECOMMENDATIONS

Is the DTC current or a history DTC?

- History – Clear the DTC
- Current and red SOS light is on - Please create a TAS case and contact TAS. If it's a Sunday or holiday, continue with diagnosis and repair, save all parts and details, contact TAS on the next available work day and review details with TAS engineer.

LINK REFERENCES

This Tech Tip does not contain any link references