



WARRANTY BULLETIN

**M0330 OUTSIDE MIRROR ADHESION LABOR
TIME CHANGE**

**WARRANTY BULLETIN NO: WB-19-021
DATE: 11-25-2019**

OVERVIEW: The following warranty bulletin is for notifying our dealers about the labor time change for the M0330 Outside Mirror Glass Adhesion recall.

Old Labor Time

b) Labor charge:

Repair	Labor
Inspection of both mirrors:	0.4 Hours
Inspection of both mirrors with replacement of 1 mirror carrier plate:	0.6 Hours
Inspection of both mirrors with replacement of 2 mirror carrier plate:	0.8 Hours

New Labor Time

b) Labor charge:

Repair	Labor
Inspection of both mirrors:	0.4 Hours
Inspection of both mirrors with replacement of 1 mirror carrier plate:	0.5 Hours
Inspection of both mirrors with replacement of 2 mirror carrier plate:	0.6 Hours

