





MPD UPDATE

Powertrain



<p>AJ20P6 Check Engine MIL with DTC P00B0-49</p> <p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - The Check Engine MIL is on. - There is a lack of power on initial acceleration <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Internal fault in the electronic supercharger is identified. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Replace electronic supercharger as required. - Raise an EPQR so the original part can be returned for analysis. 	<p>19MY Onward Range Rover, Range Rover Sport MHEV equipped with AJ20P6</p> 
KPI's	
Total VIN Count	Status
	 Matt Priestner

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

