





MPD UPDATE

Powertrain



D7A Transfer Case Replacement		18MY onward RR Velar, F PACE
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - The wheels are binding when turning the vehicle due to binding of the clutch in the transfer case. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - ICA parts development validation stage. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Perform pinpoint tests outlined in TOPIx. - If diagnosis leads to replacement of the transfer case, replace as necessary and create an EPQR so the original part can be returned for analysis. - Obtain an oil sample and hold with the original transfer case for return. 		
		
KPI's		
Total VIN Count	Status	Issue Owner
		Matt Priestner

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

