


MPD UPDATE

Body - UPDATED



Tailgate Tail Lamp Flicker	New RR Evoque 20MY
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - The tail lamps on either side of the tailgate may flicker briefly when the brake lamps are illuminated continuously for 30+ minutes in high ambient temperatures due to thermal protection of the LED lamp board. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Root cause identified as current flow being too high, causing excessive heat. - Engineering is working on a change to the lamp circuit board. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Should you find a vehicle with this concern, please report it via EQPR. 	
KPI's	
Total VIN Count	Issue Owner
	NAS: Jerry Bennett

🔴 Solution Unavailable or project not yet accepted

🟡 Solution known, not yet delivered

🟢 Service Fix Available, Communication Published

