

Classification:

Reference:

 COPYRIGHT© NISSAN NORTH AMERICA, INC.
 Date:

AT19-014

ITB19-040

November 22, 2019

2014-2015 Q50; MIL ON WITH DTC P0720 AND MAY HAVE HARSH SHIFTING AND/OR LACK OF POWER

APPLIED VEHICLES: 2014-2015 Q50 (V37)

HINT: This bulletin does not apply to Q50 Hybrid.

SERVICE INFORMATION

If DTC P0720 OUTPUT SPEED SENSOR is stored, follow the diagnostic procedure in the ESM.

If the diagnosis leads to output speed sensor replacement, replace the control valve. Do NOT replace the output speed sensor.

- Refer to the ESM for control valve replacement: TRANSMISSION DRIVELINE> TRANSAXLE TRANSMISSION > 7 AT: RE7R01A > REMOVAL AND INSTALLATION > CONTROL VALVE TCM.

HINT: The vehicle may also have harsh shifting and/or lack of power.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 22, 2019	ITB19-040	Original bulletin published

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.